

# 13042 and similar pumps

**Problem:** The pump is not sucking! – This problem may occur in case of extended non-use or because of wear-out of the sealing.

**Solution:** Prime the pump by filling in liquid through the discharge hose.

